Important Notice

Subject	Security End-of-Support Notice
主旨	安全更新支援終止公告
Affected Models	All ADLINK COM products based on: *Rockchip PX30*
Release	2026-08-28

Manual Rev.: Rev. 1.0
Release Date: August 28, 2026
Part Number: 50M-ESCOM3-10

ADLINK
LEADING EDGE AI COMPUTING

LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

Regulatory Basis

Regulatory Basis / 法規依據：EU CRA (Regulation (EU) 2024/2847), Art. 14 / NIS2 Directive (EU) 2022/2555

Revision History

Revision / 版本	Description / 描述	Date / 日期
1.0	Initial release / 初版	2026-08-28

Contents

Regulatory Basis 1

Revision History 1

1. Purpose / 本公告目的 2
2. Background — Upstream Supply Chain Constraints / 背景說明 — 上游供應鏈限制 2
3. Affected Products / 受影響產品 3
4. Recommended Migration Platforms / 建議升級替代平台 3
5. Continued Service Obligations and Customer Responsibilities / 繼續服務義務範圍與客戶責任 4
   - 5.1 ADLINK Obligations after the EoSS Date / ADLINK 於終止日後之義務 4
   - 5.2 Customer Responsibilities / 客戶責任 4

Copyright © 2026 ADLINK Technology, Inc.

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

1. Purpose / 本公告目的

This notice is issued by ADLINK Technology Inc. ("ADLINK") to all customers operating COM products based on the Rockchip PX30 platform in the European Union. It fulfils ADLINK's notification obligations under Article 14 of the EU Cyber Resilience Act (CRA, Regulation (EU) 2024/2847) and the NIS2 Directive (EU) 2022/2555.

本公告由 ADLINK Technology Inc.（下稱「ADLINK」）向所有在歐盟境內使用 Rockchip PX30 平台之 COM 產品的客戶發布。本公告旨在履行 ADLINK 根據歐盟《網路韌性法》（CRA，法規 (EU) 2024/2847）第 14 條及 NIS2 指令(EU) 2022/2555 規定之通知義務。

ADLINK hereby formally declares the End-of-Security-Support (EoSS) date for all affected Rockchip PX30-based COM products as 10 July 2026. After this date, no further security patches, BIOS updates, or microcode updates will be issued for the affected product lines.

ADLINK 正式宣告，所有受影響之 Rockchip PX30 平台 COM 產品，其安全支援終止日期（EoSS）為 2026 年 7 月 10 日。此日期之後，ADLINK 將不再針對受影響產品線發布任何安全修補、BIOS 更新或微碼更新。

2. Background — Upstream Supply Chain Constraints / 背景說明 — 上游供應鏈限制

Rockchip Electronics Co., Ltd. formally designated the PX30 microarchitecture as "Stopped" with respect to microcode security updates, specifically declining to provide mitigations for Spectre Variant 2 (CVE-2017-5715) and subsequent speculative-execution vulnerabilities. This decision was communicated via Rockchips's official Product Discontinuation Notice (PDN). Rockchip Electronics Co., Ltd.

Rockchip Electronics Co., Ltd. 正式將 PX30 微架構的微碼安全更新狀態指定為「Stopped」，明確拒絕提供幽靈漏洞變體 2（CVE-2017-5715）及後續推測執行漏洞之緩解修補。此外，Rockchip Electronics Co., Ltd. 透過正式產品停產通知（PDN）傳達，PX30 微架構之微碼安全更新狀態列為「Stopped」。

As a downstream manufacturer, ADLINK is technically unable to provide microcode-level security patches independently of Intel.

作為下游製造商，ADLINK 在技術上無法獨立於 Intel 提供微碼層級之安全修補。

Copyright © 2026 ADLINK Technology, Inc.

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

3. Affected Products / 受影響產品

The following active ADLINK COM product lines based on the Rockchip PX30 platform are subject to this End-of-Security-Support declaration. Customers should verify their specific part numbers against the table below. Products not listed should be verified with ADLINK technical support.

下列 Rockchip PX30 平台之 ADLINK COM 產品線均受本安全更新支援終止公告之約束。客戶應比對其具體料號與下表。未列出之產品請聯繫 ADLINK 技術支援確認。

Product Line / Part No.	Description / 產品說明	EoSS Date / 終止日
LEC-PX30	Short size SMARC based on Rockchip PX30	10 July 2026

4. Recommended Migration Platforms / 建議升級替代平台

ADLINK strongly recommends that customers plan migration to a currently supported platform prior to the End-of-Security-Support date of 10 July 2026. The following ADLINK product lines are recommended replacements based on form-factor and feature compatibility:

ADLINK 強烈建議客戶於安全更新支援終止日（2026 年 7 月 10 日）前，規劃遷移至現行受支援平台。以下 ADLINK 產品線為依外形規格與功能相容性建議之替代品：

EoSS Product	Recommended Product / 建議產品	Note
LEC-PX30	LEC-IMX937	LEC-IMX937 is a Short size SMARC based on NXP i.MX 937

ADLINK's technical sales team is available to provide migration assessments, including hardware compatibility analysis and software porting guidance. Please contact your regional account manager or open a support ticket at https://support.adlinktech.com.

ADLINK 技術銷售團隊可提供遷移評估服務，包括硬體相容性分析及軟體移植指導。請聯繫您的區域客戶經理，或透過 https://support.adlinktech.com 提交支援工單。

Copyright © 2026 ADLINK Technology, Inc.

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

5. Continued Service Obligations and Customer Responsibilities / 繼續服務義務範圍與客戶責任

5.1 ADLINK Obligations after the EoSS Date / ADLINK 於終止日後之義務

After 10 July 2026, ADLINK's security update obligations for Rockchip PX30 products will cease. ADLINK will not issue further BIOS, firmware, or microcode updates. BIOS updates are not applicable to Rockchip PX30 products. Article 14 incident reporting obligations under the CRA may continue to apply to any products that remain on the EU market post-EoSS; customers are advised to consult their own legal counsel regarding continued deployment obligations.

2026 年 7 月 10 日之後，ADLINK 對 Rockchip PX30 產品之安全更新義務將終止，不再發布 BIOS、韌體或微碼更新。BIOS 更新不適用於 Rockchip PX30 產品。CRA 第 14 條事件通報義務對於仍在 EU 市場流通之產品於終止日後是否持續適用，客戶應諮詢其自身法律顧問，以確認繼續部署義務。

5.2 Customer Responsibilities / 客戶責任

Customers operating PX30-based ADLINK products in critical infrastructure or essential services (as defined under NIS2) are responsible for conducting their own risk assessments and implementing compensating controls.

在 NIS2 定義之關鍵基礎設施或必要服務中操作 PX30 平台 ADLINK 產品之客戶，有責任自行進行風險評估並實施補償性控制措施。

Customers who continue to operate affected products after the EoSS date do so at their own risk, and ADLINK shall not be liable for security incidents attributable to the abovementioned unmitigable vulnerabilities.

於終止日後繼續操作受影響產品之客戶，風險自行承擔；對於前述無法緩解之漏洞引發之安全事件，ADLINK 不承擔責任。

Customers are encouraged to document their risk acceptance decisions in accordance with their internal governance frameworks and applicable national cybersecurity regulations.

建議客戶依其內部治理框架及適用之國家網路安全法規，記錄其風險接受決策。

Copyright © 2026 ADLINK Technology, Inc.

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

!!IMPORTANT NOTICE Regarding CRA Article 14 Final Report
關於 CRA 第 14 條最終報告之重要聲明

Due to the absence of any technically available corrective measure from Rockchip for PX30 microcode vulnerabilities, ADLINK is unable to submit a CRA Article 14 Final Report (required within 14 days of a corrective measure becoming available) for actively exploited vulnerabilities within this product family.
由於 Rockchip 對 PX30 微碼漏洞在技術上不存在任何可用之修補措施，ADLINK 無法就本產品系列中遭主動利用之漏洞提交 CRA 第 14 條最終報告（要求在修補措施提供後 14 日內提交）。

ADLINK will notify the relevant CSIRT of this technical constraint at the time of any Article 14 Early Warning or Notification submission.
ADLINK 將於提交任何 CRA 第 14 條早期預警或通報時，向相關 CSIRT 說明此技術限制。

Copyright © 2026 ADLINK Technology, Inc.

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000